	Liber OOCO3 Page OO37
In Accordance With P.A. 345  Chairman 200 Keel  Date Accomba 20, 1995  For corners in	
CASS COUNTY REMONUMENTATION  CASS COUNTY REMONUMENTATION  COUNTY REMONUMENTATION  COUNTY REMONUMENTATION	12-28-1995 16:08:12
1. Public Land Survey T 7 R 13 M-3	Ann L. Simmons REGISTER OF DEEDS
NORTH PORTER TWP. T R  T R	
_2. Property Controlling S T R	
-2 Missellaneous C T D	gister of Deeds Stamp & File Number
-4. Lot No, Recorded Plat	2.31
5. Private Claims	A B C D E F G H I J K L M
DALE 1. KESLER in a field survey on NOVEMBER 28, 19 95 ohereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
-IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 12 31 32 33 34 36 36
Description of original monument and accessories and/or subsequent restoration:  Dec. 25, 1826 - William Brookfield - Set post - Set by going Section 12 from East Quarter post, 40.00 Chains (2640 14" White Oak - S. 33 1/2° W. 54 Lks. (35.64') 10" White Oak - N. 51° W. 68 Links (44.88')  Apr. 4, 1877 - Amos Smith, County Surveyor - Book D, Pages Original witnesses - set post. Measured from Southeast 39.94 links (2636.04') - Witnesses for Southeast Cor. 12" Yellow Oak - N. 1/2° E. 92 1/2 Links (61.05') 18" White Oak - N. 88 1/6° W. 359 1/2 Links (237.27)  Description of corner evidence found and/or method applied in restoring or reestablishing Found 1/2" iron. The accessories of the 1989 survey to	of and 58, Identified by st corn. to East Quarter - Section 1  (Over)
location of corner. Distances to adjacent corners wer Accepted 1/2" iron as best evidence of corner.	re reasonable and consistent.
	_
	MAR 2 7 1996
	COMMISSION
Description of monument for corner and accessories established to perpetuate locating the	e position of the corner:
Set 3/4" X 24" iron pipe with aluminum cap in place of 1/2" is accepted as a careful and faithful perpetuation of the or Nail w/washer in 30" Oak tree - S. 24° 16' E. 59.30' Nail w/washer in 20" Oak tree - S. 61° 40' W. 41.0' Nail w/washer in 16" Oak tree - N. 51° 38' W. 45.55' Power, Pole - S. 34° 43' E. 46.70' Centerline gravel road - 4.0' West	iron in monument box and riginal corner.  OF MICA  DALEL.  KESLER  LAND SURVEYOR  NO.  38117
rveyor's Michigan License NoNo. 38117	IVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
	REVISED MAY 14, 1975 Revised Jan., 1983

·.

## A. Continued -

- Dec. 3, 1889 F. E. Smith, County Surveyor Book D, Page 365, Identified by witnesses marked by A. Smith, Yellow Oak cut Found good stone set. Measured brom East Quarter corner Sec. 12 to Northeast Cor. Sec. 12, 39.93 1/2 Chains (2635.71') Witnesses for NE corner Sec. 12 & SE Corner Section 1 7" Hickory S. 53° W. 63 Links (41.58') 18" White Oak N. 88 1/6° W. 359 1/2 Links (237.27')
- Oct. 13, 1972 H. Donald Peirce Set 1/2" iron bar 36" Maple S. 45 1/2° E. 79.60' NW Cor. SEc. 7-7-12 S. 82.5' Found 1/8 Cor. to S. Stone 1318.20'
- Apr. 7, 1989 Wightman-Peirce Used NE Cor. Sec. 1 SE. Cor. Sec. 1 No witnesses
- Oct. 1989 DNR Donald L. Bissell Found 1/2" iron rod. Power pole S. 30° E. 46.54'
  16" White Oak S. 67° W. 41.78'
  14" Red Oak N. 47° W. 45.60'
  5" Maple N. 20° W. 76.99'
  1/2" Rod in Monument box South 82.50'