

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 41 NR. 3-4 E.

Chippewa COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 6-7-1-12

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER	7" Cedar	N 89° W	9 links
		Marked "S 1 NBT"	
	8" Cedar	N 19° E	8 links
		Marked "S 6 NBT"	
	7" Cedar	S 32° E	6 links
		Marked "S 7 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced Section Corner from two cedar B.T.'s bearing N 35° W 31 links (in good condition, scribe marks visible) and N 58° E 26 links (in poor condition).

Corner lies 25 links south of stream C-SE and 25 links east of old winter road.

Corner found while checking lines run by D. Bonner, Ass't. District Forester.

"Old post used as Corner for many years lies 20 links west and 126 links south of Section Corner".

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 5/1/57
REGISTERED LAND SURVEYOR