

2

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T 41 .. NR 3 E ..

..... Chippewa COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 1, 2, 11, 12. ..

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap. ..

WITNESSES TO CORNER .. 12" Cedar .. N 21° E .. 16 links ..

12" Hemlock .. S 35° W .. 40 links ..

10" Cedar .. S 27° E .. 58 links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

Replaced Section Corner from one W. Birch B.T. in excellent condition;
Complete description, ~~Waze~~ and scribe mark readable.

1½" Iron Pipe in place.
Several old cedars blazed.

Corner found by Daniel Bonner, Ass't District Forester, while running
transit lines in this Township.

Corner placed and witnessed October 3, 1956.

SURVEYORS SEAL

SIGNED Billy D. Buckler .. DATE 10/15/56 ..
REGISTERED LAND SURVEYOR