

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 42 NR 4-5 E

Chippewa County COUNTY  
Drummond Island

DESCRIPTION OF CORNER Section Corner common to Sec.'s 25-36-31-30

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 8" Cedar S 78° E 68 links

Marked "S 31 NBT"

5" Cedar S 37° W 20 links

Marked "S 36 NBT"

9" Hard Maple N 34° E 30 links

Marked "S 30 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced Section Corner as perpetuated by unknown surveyor.

Found old stake, 1" pipe in concrete.

Found dead 14" W. Birch S 21° E 51 links, scribed "31 NBT"

Brush lines south, east and west. Road goes north.

SURVEYORS SEAL

SIGNED

*Silly D. Buckler*  
REGISTERED LAND SURVEYOR

DATE 5/28/57