

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Chippewa
 (County)

Located In:

Corner Code #

1. Public Land Survey
 Section Corner

T 43N R 1E A-13

T R

T R

T R

2. Property Controlling
 in Section

S T R

S T R

3. Miscellaneous
 Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED FOR RECORD
 CHIPPEWA COUNTY
 STATE OF MICHIGAN

94 JUL 22 AM 11:10

J. Roger Matthe

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on OCTOBER 3, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A-13) From 1975 ICRC, Mackinac County Records in Liber C, Page 165: "Found 1" square bolt in well box", N 40 W 91.85' 14" Poplar.

From MDOT notes 4-24-91: Found boat spike & witnessed. Measured 2640.00' to $\frac{1}{4}$ Cor. North.

1992: Neil Hill found boat spike and accepted (L.7, P.353).

N40W 91.75' Tag #3920 face 12" Cedar S55W 68.48' MDOT Tag in 6" Cedar

N60E 84.98' MDOT Tag in Power Pole S40E 137.01 MDOT Tag in 14" Cedar

North 2640.07' $\frac{1}{4}$ Corner South 2661.04' $\frac{1}{4}$ Corner

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A-13) Found corner and accessories as recorded in Liber 7, Page 353 of the Chippewa County Records. Accepted corner position as found.

**SURVEY &
 REMONUMENTATION**

JUL 26 1994

COMMISSION



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A-13) Boat spike in monument box located approximately 1' East of ex. centerline M-129.

WITNESSES

N 40 W	91.75'	Tag #3920 face 12" Cedar
S 55 W	68.48'	MDOT Tag in 6" Cedar
N 60 E	84.98'	MDOT Tag in Power Pole
S 40 E	137.01	MDOT Tag in 14" Cedar
North	2640.07'	$\frac{1}{4}$ Corner
South	2661.04'	$\frac{1}{4}$ Corner

Signed by Keith R. Waters

Date 7-22-94

Surveyor's Michigan License No. 33142

NOTE: Bearings are compass bearings corrected for declination.

Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
 REVISED MAY 14, 1975
 REVISED JAN., 1983