

MAR 09 1994

COMMISSION

Chippewa County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED FOR RECORD  
CHIPPEWA COUNTY  
STATE OF MICHIGAN

93 DEC 29 AM 10:28

For corners in

Chippewa

(County)

Located in:

Corner Code ##

1. Public Land Survey

T 44N R 1E

G-8

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

J. Roger Malott

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Larry R. Rogers, in a field survey on November 18, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G-8) 1/2 Corner Common to Sections 21 & 22, T44N-R1E

C.M. Cade set an iron pipe and witness monument 33' East as part of a 1930 survey of the Munoscong State Forest. In 1972, Billy Buckler found witness monument and placed 1" x 11" square iron in road and recorded it in Liber 1 Page 44 of the Chippewa County Corner Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G-8) This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found Cade witness monument and 1" iron pipe 39" below grade of paved road. Corner position works well with witness monument and distances to Section corners North and South match 1930 Cade survey. Accepted corner position as found and placed 3/4" x 24" iron pin over found pipe to bring to surface of road.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G-8) Corner is a 3/4" x 24" iron pin with plastic remonumentation cap set over 1" iron pipe (39" deep), 2.6' East of centerline of Riverside Drive on extension of fence lines East and West.

Witnesses: Fence Post	N43°W	71.34'
Fence Post	S55°W	59.87'
Utility Pole (PD2/21/23)	S35°E	74.51'
"V" Cut in South End 24" C.M.P.	N40°E	73.65'
DNR Witness Monument (#20)	S88°E	32.70'

Signed by

Date 27 DEC 1993

Surveyor's Michigan License No. 29251

NOTE: Bearings are compass bearings corrected for declination.  
Distances are to a nail in side of witness objects unless noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

