

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES
LAND CORNER RECORD


Chippewa COUNTY
T 44N R 1E

DESCRIPTION OF CORNER SW Corner of the East $\frac{1}{2}$ of the East $\frac{1}{2}$ of the NE $\frac{1}{4}$ of Sec. 15

CORNER MONUMENT 4" iron pipe filled with concrete 4.0' long

DATE MONUMENT PLACED AND WITNESSED May 16, 1972

WITNESSES TO CORNER..... 6" Spruce S60°W 13.3'



16" Spruce N87°E 29.9'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Corner lies on low Spruce aspen ridge 655.0' West of East $\frac{1}{4}$ Corner.

SURVEYOR'S SEAL

DISTRIBUTION:

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE

6/20/72

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing

R 4047
Rev. 10/68