## SURVEY & REMONUMENTATION -

FEB 2 3 2001

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

Chippewa County Remonumentation Corner 100 LAND CORNER

For corners in	
----------------	--

Chippewa County L	ocated in:	Corner Code #
Property Controlling in Section S. Miscellaneous Property in Sec. S.	TR	G-9

42.00 MSSR 2 FEB 2001 3:49:56 PM Receipt #1103 RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

PAGE 193 ROOK 11

Register of Deeds Stamp & File Number


4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

## G-9 Corner Common to Sections 21, 22, 27 & 28, T44N, R1W.

1845 - Original corner established by James H. Mullett. Witnesses: Hemlock 12, S70°E 39 links - Hemlock 20, N32°W 19 links.

Circa 1930 - Chippewa County Surveyor corner witness book shows a 15" concrete monument with white sand-stone at gravel surface, with an assortment of witness objects.

1971 - Michigan Department of Transportation right-of-way maps for Highway M-48. Section corner G-9 is shown as as a P.I. at Station 692+98.39.

1991 - Keith R. Waters, P.S. 33142, LCRC Liber 7, page 344, Chippewa County corner records. Found annually bar in a monument box. Location fits with M.D.O.T. right-of-way maps. Witnesses:

5" Aspen, N40°W 122.05'

8" Aspen, N06°W 103.40'

5" Aspen, S19°W 68.47'

8" White Birch, S26°E 87.18'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 1" iron bar in a monument box in the approximate centerline of Highway M-48. Two of the record bearing trees from the 1991 LCRC have been cut down, one is alive and standing, one is dead and standing.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1" iron bar in a monument box at the corner location, which falls in the approximate centerline of Highway M-48, at a 2 track road to the south. TE OF MICHIGAN

Witnesses:

Nail and plastic witness tag #33142 in Power Pole, N68°W 191.62' Nail and plastic witness tag #33142 in Power Pole (PD4/70), N58°E 152.76'

Nail and plastic witness tag #33142 in 12" White Birch, S12°E 66.33'

Nail and plastic witness tag #33142 in 5" Spruce, S10°W 59.22'

Nail in 5" Aspen, S19°W 68.47'

Date 12-29-00

Keite R. Water

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED JAN., 1983
REVISED JOCT., 1995

MAN SHARE

SUR

KEITH R

WATERS

PROFESSIONAL.

23 3 1 4 South of the state of