FEB 23 2001

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Chippewa County Remonumentation Corner

SECTION

For corners in

744N M4144 11.0
T44N R1W H-9 T R T R T R
TR TR R
T

PAGE 179 PROOK 11

\$7.00 LAND CORNER

\$2.00 MSSR

c D Ε

2 3

2 FEB 2001 3:42:51 PM Receirt #1103 RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF HICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

> G н

Register of Deeds Stamp & File Number

4 Lot No.

Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

5 6 7 8 9 10

A. Description of original monument and accessories and/or subsequent restoration:

H-9 1/4 Corner Common to Sections 22 & 27, T44N, R1W.

1845 - Original corner established by James H. Mullett. Witnesses: Willow 4, N34°W 13 links - Cedar 4, S10°E 14 links.

1999 – Keith R. Waters, P.S. 33142, Certificate of Survey in Section 27, Town 44 North, Range 1 West.

Set ½" iron with cap #33142. Witnesses:

Power Pole, N42°E 94.31'

7" Aspen, S60°W 113.43' 10" Aspen, S02°W 65.02'

7" White Birch, S52°E 119.25'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 1/2" iron with cap #33142 in the approximate centerline of Highway M-48. Also found all four of the witness objects as called for in the above mentioned Certificate of Survey. The found iron is mid-way and on line between the section corners at G-9 to the west and at I-9 to the east. Replaced the found 1/2" iron with a 3/4" rebar and Chippewa County Remonumentation cap in a monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a ¾" x 24" rebar with a Chippewa County Remonumentation cap in a monument box at the corner location, replacing a found 1/2" iron with cap #33142. Corner falls in the approximate centerline of Highway M-48.

Witnesses:

Nail and plastic witness tag #33142 in Power Pole, N42°E 94.31'

Nail and plastic witness tag #33142 in 7" Aspen, S60°W 113.43'

Nail and plastic witness tag #33142 in 10" Aspen, S02°W 65.02'

Nail and plastic witness tag #33142 in 7" White Birch, S52°E 119.25"

STEOF MICHIGAL WATERS PROFESSIONAL SURVEYOR Ho. 33142 " Konnana and c, Cression

Signed by Kelly R. Water

Date 12-29,-00

Surveyor's Michigan License No. 33142