

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

BOOK 11 PAGE 181

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T44N R1W I-2

T
T
T
T
T
T
T

2. Property Controlling

S

T

In Section

S

T

3. Miscellaneous

S

T

Property in Sec.

S

T

**SURVEY &
REMONUMENTATION**

FEB 23 2001

4. Lot No.

, Recorded Plat

5. Private Claims

SECTION

I, Keith R. Waters, in a field survey on November 8, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-2 1/4 Corner Common to Sections 2 & 3, T44N, R1W.

1845 - Original corner established by James H. Mullett.

Witnesses: Hemlock 12, N20°E 21 links - Hemlock 10, S20°W 11 links.

1962 - Billy D. Buckler, RLS 8887, Michigan Department of Conservation Land Corner Record, Liber 3, page 126, Chippewa County corner records. Corner reestablished by single proportionate measurement and on line between two section corners. Corner lies on east edge of north-south road and 48 links south of road on east. 1" pipe with aluminum cap. Witnesses:
8" Soft Maple (1/4 S NBT), N43°W 111 links
10" Soft Maple (1/4 S NBT), S64°W 106 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1" pipe with remains of a broken aluminum DNR cap and one of the bearing trees as called for in the above mentioned 1962 records. Placed a plastic Chippewa County Remonumentation cap inside the found pipe and established additional bearing trees.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1" pipe at the corner location, which falls 15'± east of a north-south road. Placed a plastic Chippewa County Remonumentation cap inside the found pipe.

Witnesses:

Nail and plastic witness tag #33142 in 12" Red Maple, S68°W 70.26'

Nail and plastic witness tag #33142 in 12" Red Pine, S18°E 47.55'

Nail and plastic witness tag #33142 in 10" Red Pine, S38°E 33.21'

Nail and plastic witness tag #33142 in 12" Red Pine, N80°E 25.06'

Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142

\$7.00 LAND CORNER

\$2.00 MSSR

2 FEB 2001 3:43:28 PM Receipt #1103

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3	•	2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

