

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner

BOOK 11

PAGE 184

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T44N R1W I-5

T

R

T

R

T

R

2. Property Controlling  
in Section

S

T

R

S

T

R

3. Miscellaneous  
Property in Sec.

S

T

R

S

T

R

**SURVEY &  
REMONUMENTATION**

**FEB 23 2001**

\$7.00 LAND CORNER

\$2.00 MSSR

2 FEB 2001 3:47:15 PM Receipt #1103

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

**SECTION**

I, Keith R. Waters, in a field survey on November 10, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-5 Corner Common to Sections 10, 11, 14 & 15, T44N, R1W.

1845 - Original corner established by James H. Mullett.

Witnesses: Hemlock 20, S65°E 15 links - Hemlock 16, N35°W 27 links.

1918 - Chippewa County Surveyor Frederick H. Brown, RLS 944. Brown's notes for Section 14 indicate that this is probably "Stillwell's" corner, at intersection of roads north and east.

1925 - Chippewa County Surveyor corner tie book. Brown & Colwell reference a 15" concrete monument.

1946 - Chippewa County Surveyor Rudolph H. Larsen, RLS 3644. Notes show a post at road intersection.

1962 - Billy D. Buckler, RLS 8887, Michigan Department of Conservation Land Corner Record, Liber 3, page 139, Chippewa County corner records. Corner placed in road intersection, agrees with records of fences to east. Witnesses: 13" Red Pine (S 14 NBT), S66°E 145 links - 20" White Pine (NBT), S51°W 50 links.

1987 - Gerald L. Wiggins, RLS 23521, LCRC Liber 7, page 37, Chippewa County corner records. Remonument set by Billy D. Buckler. Witnesses:

12" Red Pine, N41°W 54.9'

12" Red Pine, N69°W 74.4'

10" Spruce, S11°E 39.7'

12" Red Pine, S63°E 92.5'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1" pipe with a brass Department of Conservation cap and established new witness objects. The distance to the section corner on the meridian at M-7 two miles to the east is within 1.8 feet of that as shown in the above mentioned County Surveyor notes by Frederick H. Brown.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1" pipe with a brass Department of Conservation cap at the corner location, which falls at the approximate centerline P.I. of roads to the east and north.

Witnesses:

Nail and plastic witness tag #22428 in 12" Red Pine, N78°W 74.87'

Nail and plastic witness tag #22428 in 12" Red Maple in clump, N22°W 70.65'

Nail and plastic witness tag #22428 in 6" Twin Red Maple, S50°W 35.57'

Nail and plastic witness tag #33142 in 4" x 6" Wood Post (MBT), S74°E 22.12'

Signed by Keith R. Waters

Date 12-29-00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983  
REVISED OCT., 1995