

SUBJECT
REMONUMENTATION
MAP 11/6/98

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner \$7.00 LAND CORNER

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey

T44N R2W E-5

2. Property Controlling
in Section

S T R
S T R
S T R
S T R

3. Miscellaneous
Property in Sec.

4. Lot No.

, Recorded Plat

5. Private Claims

\$2.00 MSSR

5 MAR 1999 1:57:13 PM Receipt #14029

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 11 PAGE 9

Register of Deeds Stamp & File Number

I, Keith R. Waters, in a field survey on April 2, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-5 Corner Common to Sections 8, 9, 16, & 17, T44N, R2W

1845 - Original corner established by James Mullett.

Witnesses: Tamarack 10, S45°E 16 links - Birch 12, N43°W 10 links.

1897 - Chippewa County Surveyor Frederick H. Brown, RLS 944. Notes for Section 17 show this corner, "divided up on 8, 17, & 20, round cedar post."

1907 - County Surveyor Brown's notes for Section 8 call this corner a "Carleton Corner."

1915 - County Surveyor Brown's notes for Section 9 call this corner a "Carleton Corner."

Circa 1930's - Chippewa County Surveyor corner tie book shows this corner with various witnesses.

1959 - Liber 3, page 225, Chippewa County corner records. Michigan State Highway Department surveyor Ray Walker, found 1/2" iron pin in 6" post. Witnesses:

Guy Pole, S42°E 41.13' - Telephone Pole, S51°W 37.35' - Fence Post, N44°W 45.52'.

1959 - Liber 3, page 227, Chippewa County corner records. Michigan State Highway Department surveyor Ray Walker, this corner is a 1" iron pipe in wood post. Witnesses:

Guy Pole, S40°E 41.43' - Power Pole, N47°E 42.57' - Telephone Pole, S52°W 37.27'.

1973 - Certificate of Survey, liber 1 of surveys, page 49. Neree D. Alix, RLS 6254, shows a 1" iron pipe with same witnesses as 1959 records (liber 3, page 227).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Found a 1" iron pipe at the intersection of Centerline Road and 20 Mile Road. All record witnesses mentioned above are gone. Accepted corner as found and established new witness objects.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 1" iron pipe at the corner location, which falls at the centerline intersection of Centerline Road north-south and 20 Mile Road east-west. Witnesses:

Nail and witness tag #22428 in side of Power Pole (RU2/61), N48°W 52.08'

Nail and witness tag #22428 in side of Power Pole, N70°E 69.59'

Nail and witness tag #22428 in side of Corner Fence Post, S52°E 54.42'

"V" notch in Top End of Culvert, S70°W 44.16'

Signed by Keith R. Waters

Date 12-30-98

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1985

T44N R2W E-5

BOOK 11 PAGE 9

11 9