APR 0 7 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Chippewa County Remonumentation Corner, 00 LAND CORNER

For corners in SECTION

Chippewa County	Located	l in:		Corner Code #
Public Land Survey		T45N T T T	R2W R R R	I-9
the Country	S S	† T	R	
Miscellaneous Property in Sec.	S S	T T	R R R	

\$2.00 MSSR 6 Mar 1998 2:00:13 PM Receipt #6451 RECEIVED FOR RECORD CHIPPENA COUNTY - STATE OF MICHIGAN SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 198

С D F F G

8

13

Register of Deeds Stamp & File Number

28

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on November 3, 1997, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-9 Corner common to Sections 22, 23, 26, & 27, T45N, R2W

1849 - Original corner (spruce post) was established by Harvey Mellen, D.S. Witnesses: Spruce 8, N64°E 17 links - Yellow Birch 12, S53°W 39 links

Circa 1920 - Chippewa County Surveyor Frederick H. Brown notes for Sections 23 and 26 indicate that he found at this corner, probably established by a railroad surveyor.

Circa 1930 - Chippewa County Surveyor corner tie book shows a cement post at corner location. Witnesses: S. Maple, N65°W 104' - 10" Jack Pine, S731/2°W 129' - 10" Jack Pine, S71°E 141'.

1959 - Ray Walker, Michigan State Highway Department, liber 2, page 238, Chippewa County corner records. Found 4" x 4" square post. Witnesses: 6" Poplar, S64°W 13.65' - 6" Poplar, N20°W 48.15' - 14" Pine, S10°E 58.60'.

1980 - LCRC liber 4, page 272, James H. Granger, RLS 16041. Found a ¾" pipe in center of road. Witnesses: 14" W Birch, N13°E 60.80' - 10" J Pine, N52°E 80.48' - 26" W Pine, S06°E 87.78' - 1" Galv. Pipe, S06°W 37.57'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being perpetuated as part of the Chippewa County Remonumentation Program. Found a 3/4" iron 8" below the surface of asphalt pavement of east-west road, at the surface of old asphalt road, which has been recently raised and rebuilt. Also found the bearing tree shown in the 1980 LCRC as a 26" white pine (It is actually a 16" jack pine). Bearing and distance from found iron to jack pine check well. Accepted corner location as found, placed a 3/4" rebar over found iron, and established new witness objects.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed a 3/4" x 24" rebar with a plastic Chippewa County Remonumentation cap over a found 3/4" iron at the corner location, which falls 0.6 feet north of the centerline of an east-west asphalt road (Ploegstra Road). Witnesses:

16" Jack Pine, S06°E 87.66' 7" Balsam Fir, S32°W 67,28' 7" Spruce, N02°E 62.04' 9" White Pine, N37°W 71.17"

Note: Distances are to a nail/tag #33142 in the side of the tree. Trees are blazed and painted.

Surveyor's Michigan License No. 33142

Bearings are compass bearings corrected for declination.

Keith R. Wat

Date (2-30-47

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995

KEITH R WATERS

PROFESSIONAL SURVEYOR

No.

POFESSION