

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Chippewa

(County)

Located In:

Corner Code #

1. Public Land Survey

T R
T R
T R
T R

2. Property Controlling in Section

S 18 T 45N R 2W 3
S 18 T 45N R 2W 4

3. Miscellaneous Property in Sec.

S T R
S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Apr 26 2001

I, Stephan J. Szyszkoski, in a field survey on , 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:


(3-Sec. 18) North 1/16 corner between Sec. 18, T45N-R02W and Sec. 13, T45N-R03W. Not established in the original survey.
(4-Sec. 18) Northwest 1/16 corner, Section 18. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(3-Sec. 18) Established the corner midway and on a line of mean true bearing between Quarter corner 1318.44' south and Section corner 1318.44' north.
(4-Sec. 18) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

| | | | |
|---|------------------------------|--|-------------------------------|
| (3) Set 1"IDx36" I. Pipe with 4" alum. MDNR cap. Blazed, scribed, and set meas. nails in: 6" Maple S05W 10.2' 14" Maple S70E 10.0' 5" Maple N15W 17.9' 12" Maple N65W 21.8' Bearings are magnetic. Distances are to nail with tag. | "N1/16 BT" do do do | (4) Set 1"IDx36" F. Pipe with 4" alum. MDNR cap. Blazed, scribed, and set meas. nails in: 8" Maple N71W 15.15' 12" Maple S72W 2.9' 6" Maple N38E 12.45' 6" Maple N10W 18.3' 4"x6" treated post adjacent. Bearings are magnetic. Distances to nail with tag. | "NW1/16 BT" do do do |
|---|------------------------------|--|-------------------------------|



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 2/14/02

For the Michigan Department of Natural Resources - Office of Property Management