

STATE OF MICHIGAN
DEPARTMENT
OF
NATURAL RESOURCES

LAND CORNER RECORD

Chippewa COUNTY


T 45N R 7W

DESCRIPTION OF CORNER $\frac{1}{4}$ Cor. bet. secs. 24-25

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 8/2/71

WITNESSES TO CORNER..... 8" Cedar ($\frac{1}{4}$ S NBT) S18°W 26.8'



8" Cedar ($\frac{1}{4}$ S NBT) S42°E 31.8'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established midway bet. two sec. cors. and in a old E-W log road.
Found several old blazes to south, facing this location.

Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

SIGNED

Billy D. Buckler

REGISTERED LAND SURVEYOR

DATE

1/10/72

DISTRIBUTION:

County Courthouse
Area Forester (Regions I & II)
District or Region Surveyor
Forestry Div., Lansing