

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 45N N.R. 7W


Chippewa COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 13-14-23-24

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 12-15-70

WITNESSES TO CORNER..... 12" W. Pine (S24 NBT) S80° E 64.5'



CIRCLE CORNER REGISTERED

14" W. Pine (S23 NBT) South 73.5'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner re-established by proportionate measure to good corners; one mile east and one mile west, and on a blazed line to east. Found blazes to north of the corner.

No evidence of Hemlock bearing trees.

Position checks with corners to south.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
Billy D. Buckler DATE 1-21-71  
REGISTERED LAND SURVEYOR