

DEC 18 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970
Chippewa County Remonumentation Corner

For corners in

SECTION

Chippewa

Located In:

Corner Code #

1. Public Land Survey

T 46N R 2E

C-4

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, Larry R. Rogers in a field survey on October 15, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C-4) 1/4 Corner Common to Sections 7 and 8, Township 46 North, Range 2 East.

A 6" aspen was marked at the original corner position in 1845 by James H. Mullett. County Surveyor records make no specific reference to corner. In a 1975 B.L.M. dependent resurvey the corner position was re-established "latitudinally at proportionate dist." and longitudinally on the projection of a blazed line to the N", but attached plat of survey shows corner to be set midway and on-line between Northeast and Southeast corners of Section 7.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C-4) 1/4 Corner Common to Sections 7 and 8, Township 46 North, Range 2 East.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Recovered B.L.M. 2 1/2" iron pipe with stamped brass cap and both witness trees - now both dead. Distance to Northeast corner of Section 7 is 2643.24 feet (B.L.M. 2641.98 feet) and distance to Southeast Corner of Section 7 is 2643.71 feet (B.L.M. 2641.98 feet). Corner is within 0.4 feet of being midway and on line between Northeast and Southeast corners of Section 7. Accepted corner position as found and established four new witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C-4) 1/4 Corner Common to Sections 7 and 8, Township 46 North, Range 2 East.

Corner is a 2 1/2" iron pipe with stamped B.L.M. aluminum cap 6" above ground.

Witnesses:

15" Maple	S17°E	57.48 feet
10" Ash	N39°E	16.46 feet
14" Maple	S72°E	40.72 feet
12" Ash	S75°W	22.86 feet
Remains of Cedar Post	N60°W	1.9 feet

Signed by

Date

30 DEC 1998

Surveyor's Michigan License No. 29251

NOTE: All bearings are compass bearings corrected for declination (6°W). All distances are to a nail and tag in the side of witness object unless otherwise noted.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

wp:wpdocs\larry\corner\46n2e.c-4

\$17.00 LAND CORNER

\$2.00 HSSR

21 JAN 1999 10:13:40 AM Receipt #13123

RECEIVED FOR RECORD

CHIPPewa COUNTY - STATE OF MICHIGAN
SHARON H. KENNEDY, REGISTER OF DEEDS

BOOK 10 PAGE 334

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3			2		1	
3													
4	7		8		9		10			11		12	
5													
6	18		17		16		15			14		13	
7													
8	19		20		21		22			23		24	
9													
10	30		29		28		27			26		25	
11													
12	31		32		33		34			35		36	
13													



BOOK 10 PAGE 334