

SECTION

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**  
**Chippewa County Remonumentation Corner**

For corners in

Chippewa County

Located in:

Corner Code #

1. Public Land Survey T47N R1W K-2/K-3

T	R	
T	R	
T	R	#12

2. Property Controlling S T R  
in Section S T R3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

BOOK 11 PAGE 65

\$7.00 LAND CORNER

\$2.00 HSSR

23 FEB 2000 3:27:07 PM Receipt #211

RECEIVED FOR RECORD

CHIPPEWA COUNTY - STATE OF MICHIGAN

SHARON H. KENNEDY, REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

I, William L. Karr, in a field survey on December 7, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K-2 / K-3) Meander Corner Between Sections 1 and 2, T. 47 N., R. 1 W.

1845 James H. Mullett set post for corner in original survey, 5.00 chs North of section corner.

1854 Thomas Whelpley, U.S. Survey of Private Claim No. 1, Sault Ste. Marie. Field notes show Whelpley recovered the original section and meander corners and measured 4.60 chs between them.

1901 F.H. Brown, Plan of Bradley Watkins and Co. Mill and Docks in County Surveyors office, plat book #1. The drawing shows the North and East lines of fractional section 2, the position of the meander corner being in the water 303.6' North of the section corner.

1912 F.H. Brown, additional survey work for Bradley Watkins Company. Drawings in County Surveyors office show no indication of the meander corner being monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K-2 / K-3) Meander Corner Between Sections 1 and 2, T. 47 N., R. 1 W.

This corner is being perpetuated as part of the Chippewa County Remonumentation Program.

Could find no evidence of the original corner or of subsequent restoration. Brown appears to have used Whelpley's distance for his surveys (4.60 chs), however at the time of his surveys the meander corner appears to fall in the water. Presently the area around the meander corner has been filled in to form a large peninsula which extends several hundred feet beyond the original shoreline forming the former Reiss Coal Docks.

Re-established the meander corner by extending the section line from the South the original G.L.O. distance, 330.00' (5.00 chs) North from the section corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K-2 / K-3) Meander Corner Between Sections 1 and 2, T. 47 N., R. 1 W.

Corner is a 3/4" x 24" iron with a stamped aluminum Chippewa County Remonumentation cap.

Witnesses:	6" White Birch	N 45° E	109.12'
	6" White Birch	S 13° E	34.48'
	4" White Birch	S 48° W	34.04'
	SW corner of conc.	N 46° W	233.94'
	Block storage shed		

BOOK 11 PAGE 65

Bearings are compass bearings, corrected for declination (7° W), trees are blazed and all distances are to a nail and tag in the side of the witness object unless otherwise noted.

Signed by

William L. Karr

Date

12-23-99

Surveyor's Michigan License No. 27450

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1976

REVISED JAN. 1993

REGISTERED LAND SURVEYOR