CLACY 8

MAR 0 9 1994

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF MICHIGAR

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 93 DEC 29 AH 10: 24

			11 10: VI
For corners in COMM	(SSICN Filing Requir	ement of Act 74, Mich. P.A. 1	
For corners in "			O Rose M. 1 11
Chippewa	Located in:	Corner Code ##	J. Roga Malsike
(County)			REGISTER OF CLEDS
4 Bullion Land Comme	T Arms D des	7 12	THE OWNER OF STEEDS
Public Land Survey	T_47N_R_1W	A-13\	
	T 47N B 2W 0		
	T_46N_R1W_	A-1 Corner	
2. Property Controlling	T_46NLR_2W_ STR	M-1 /	
in Section	S T R		
3. Miscellaneous	.S T R		
Property in Sec.	S T R		Register of Deeds Stamp & File Number
			· · · · · · · · · · · · · · · · · · ·
	, Recorded Plat		A B C D E F G H I J K L M
5. Private Claims			
		•	2 6 5 5 4 3 4 2 4 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			3
			4 - 7 - 8 - 1 - 9 - 1 - 10 - 11 - 12 - 12 - 12 - 12 - 12
i William L. Karr	C_, in a field survey onMay_2	19 _93	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			
	istructions of the United States Depa	•	
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a,			
Court of Law; established, re-established, monumented, re-monumented, recovered, found as			5
expressed below:			20 72 720 720 720
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			
on this certifica	ne.		12 31 32 33 34 35 36
			13

A. Description of original monument and accessories and/or subsequent restoration: (A-1) Township Corner Common to Sections 1 (T46N-R1W), 6, 31 & 36.

William L. Karr, L.S. 27450, recorded in Liber 6, Page 367 of the Chippewa 1985: County Corner Records. Set ½" iron, L.S. 27450, in a monument box.

Power Pole (E 112) S65°E 113.21'

Metal Sign Post (3" diameter) S16°W 57.95' Power Pole (E 113) S68°W 136.53'

10" White Birch N17°W 81.45'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

is being perpetuated as part corner \mathbf{of} the Chippewa Remonumentation Program.

Found record corner and witnesses. Accepted corner position as found and added an additional witness.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner is a 1/2" iron L.S. 27450 in a monument box in the centerline of Six Mile (A-1)Road.

Witnesses:

Power Pole (E 112)	S65°E	113.08'
Metal Sign Post (Base)	S16°W	58.10'
Power Pole (E 113)	S68°W	136.53'
10" White Birch	N17°W	81.58'
Northwest Corner of Concrete Pad	1127 11	01.100

for Utility Box S48°E 64.44'

Signed by

Surveyor's Michigan License No. 27450
NOTE: Bearings are compass bearings corrected for declination. Revised MAY 14, 1975 27450 REVISED MAY 14, 1975 REVISED JAN., 1983 Distances are to a nail in side of witness objects unless noted.

KARR LAND SURVEYOR