

For corners in

(County)

**Located In:**

Corner Code #

- |                         |    |     |       |
|-------------------------|----|-----|-------|
| 1. Public Land Survey   | T  | R   |       |
|                         | T  | R   |       |
|                         | T  | R   |       |
|                         | S  | T   | R     |
| 2. Property Controlling | S  | T   | R     |
| in Section              | 33 | 50N | 6W 13 |
|                         | S  | T   | R     |
| 3. Miscellaneous        | S  | T   | R     |
| Property in Sec.        | S  | T   | R     |

**Register of Deeds Stamp & File Number**

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

JUN 12 2007

I, Stephan J. Szyszkoski, in a field survey on                     , 20       do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 33) Southeast 1/16 corner, Section 33. Not established in the original survey.

[illegible]

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 33) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The position for the corner falls in the Betsy River and was not monumented. Placed a Witness Corner on the 1/16 line 10.89' South of the position of the corner. From the WC, the top of the southerly river bank is 6' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx36" I.pipe with 4" alum.  
MDNR cap for a Witness Corner. Set  
measuring nails in:

10" Maple North 5.05'	mrkd "WC BT"
14" twin Maple S20E 4.95'	do
9" Maple S61W 26.37'	do
18" W.Birch S17W 18.04'	do

Bearings are magnetic. Distances are to  
nail with tag.



Signed by

Date \_\_\_\_\_

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
Revised May 14, 1975  
Revised Jan., 1983  
Revised Oct., 1995