

SURVEY &
REMONUMENTATION

FEB 18 1994

CLARE COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
CLARE
(County)

Located In:

Corner Code ##

1. Public Land Survey

T 17N R 4W

C-5

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECEIVED
E 10 40

1993 DEC 20 PM 1:46

REGISTER OF DEEDS
CLARE COUNTY
DONNA M. CARR

Register of Deeds Stamp & File Number

I, MARK R. ROBISON, in a field survey on OCTOBER, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1850 W.A. BURT POST W. PINE 24" N 65°W 32 LKS
W. PINE 20" S 39°W 43 LKS

10-26-03 A. JOHNSON, CSR 4-34

10-10-10 A. JOHNSON, CSR 2-02

NO DATE A. JOHNSON, CSR 5-161

5-1-72 LAPHAM, LCRC 25-72

10-17-72 URBANIAK, (132) 1-375

9-5-79 LAPHAM, IRON IN MON. BOX, LCRC 352-79

9-5-79 LAPHAM, IRON IN MON. BOX, LCRC 353-79

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON IN MON. BOX ON FILL SECTION FOR EXPRESSWAY OVERPASS.

DID NOT FIND WITNESSES FOR CORNER PRIOR TO 9-5-79.

FOUND 9-5-79 WITNESSES.

MEASURED SOUTH TO 1/8 CORNER AND 1/4 CORNER ACCORDING TO SURVEY RECORDED IN LIBER 1, PAGE 375.

DISTANCE AND ALIGNMENT IS SUBSTANTIALLY CORRECT.

ACCEPTED IRON IN MON. BOX AS BEST PERPETUATION OF ACCEPTED CORNER.

This Corner established in Clare County Remonumentation Program.
See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8" x 36" RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP IN MON. BOX.

WEST, 18.80' - NAIL & TAG, GUARD RAIL POST

EAST, 19.90' - NAIL & TAG, GUARD RAIL POST

N 35°E, 31.95' - NAIL & TAG, GUARD RAIL POST

N 35°W, 32.74' - NAIL & TAG, GUARD RAIL POST



Signed by

Mark R. Robison

Date

11/24/93

Surveyor's Michigan License No.

27458