

NOV 1 8 1997

4. Lot No. 5. Private Claims

CLARE COUNTY REMONUMENTATION

	CO	M	Mi	6 2 C	المراج ا	in the
--	----	---	----	-------	----------	--------

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

=	RECEIVE! # 243-97 97 NOV -4 PH 3:16
•	REGISTER OF DEEDS CLARE COUNTY CAROL A. HOAULAY
	Register of Deeds Stamp & File Number

For corners in				
CLARE	Located In:		Corner Code #	
(County)				
1. Public Land Survey	T 20N F		G-4	
	TF	=		
2. Property Controlling in Section	S TF S TF	₹		
3. Miscellaneous Property in Sec.	S TF S TF	₹ ₹		
t telescope and				

, Recorded Plat

MARK R. ROBISON in a field survey on July 1 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 1 and 2 above were in the corner points mentioned in lines 1 and 2 above were in the corner points mentioned in lines 1 and 2 above were in the current manual of survey instructions of the lines o Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: 6-23-86 J. Ray (132) 2-942 References Corner in Sec. Subd. 1856 Coleman Set qr. Sec. Post

9-20-74 McClung L.C.R.C.# 194 & (132) 1-927 Fd. 1/2" Pipe Wit.-S75W 48.50: 16" R. Pine N35E 94.00 W. Oak N82E 41.35: 14" Tamarak

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 1/2" x 15" pipe over 18" T-bar. Found all 1974 witnesses. Excavated but found no other evidence.

See dossier for detailed report.

APPROVED LAND CORNER P.A. 345 of 1990

Clare Gounty Chairman 4

Date_

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

G-4; 1/4 Corner common to Sections 9 & 10. Set 5/8" x 36" rerod with 3" Clare County Monument Cap marked P.S.#27458. Accepted as best available evidence of accepted position of the corner.

Witnesses:

N35E 94.00', nail & tag, 24" W. Oak (OBT) N82E 41.35', nail & tag, 18" Tamarack (OBT) S16E 67.32', nail & tag, 24" W. Pine

N40W 43.62', nail & tag, 6" Balsam

Anu (00 Signed by Surveyor's Michigan License No._ 27458

Date 10-31-97

5