

SURVEY & REMONUMENTATION

FEB 02 1998

REMONUMENTATION SECTION 36, BATH TOWNSHIP LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

11RFR

4 PAGE 254

For corners in
Clinton
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|----|---|----|------|
| 1. Public Land Survey | T | 5N | R | 1W | M-12 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | R | | |
| | S | T | R | | |
| 3. Miscellaneous Property in Sec. | S | T | R | | |
| | S | T | R | | |

RECORDED

DEC 22 11 06 AM '97

REGISTER OF DEEDS
CLINTON COUNTY, MICH.
Register of Deeds Stamp & File Number
(Carol W. Coffey)

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Arden S. Pierson, PS, in a field survey on July 31 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- ◆ Original survey by Joseph Wampler, DS, 1824. Set 1/4 Mile Post, witnessed by: W.O.3" - N34-1/2°W - 24 links; W.O.6" - S9-1/2°W - 58 links.
- ◆ Plat of Bonnie Meadows Estates No. 1, Liber 374, pages 272-274, dated May 1, 1979.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Located concrete monument at the Northeast corner of the Plat of Bonnie Meadows Estates No. 1, projected a line from the SE corner of section 36, through said NE corner the recorded distance of 2658.18 feet to the corner position. Accepted this point as a careful and faithful reestablishment of the position of the original corner - set standard Clinton County monument.

(SEE BACK OF SHEET FOR RELATIONSHIP OF LINE TO IRONS FOUND)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

East 1/4 Corner, Section 36

*Standard Clinton County Monument

- Nail & tag #13039 in NW side 9" Elm - N41°E - 13.63'
- Nail & tag #13039 in SW side 8" Oak - S41°E - 15.16'
- Nail & tag #13039 in West side 12" Elm - S2°E - 32.52'
- Nail & tag #13039 in South side 32" Maple - N85°W - 25.24'

4.6' East of fence line North & South

*Standard Clinton County Monument is a 2 1/4" diameter Steel tube 30" long with a stamped brass cap and a breakaway magnetic base.

APPROVED BY
CLINTON COUNTY PEER GROUP
DATED 9/24/97
J 78



Signed by Arden S. Pierson

Date July 31, 1997

Surveyor's Michigan License No. 13039