

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey	T	25N	R	3W	D-5
	T	25N	R	3W	E-5
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on January 19, 2001 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		8		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

D-5 G.L.O. Addison P. Brewer D.S. August 1852

Set quarter section post

Wit: Yellow Pine 12 N73°E 41 links

Yellow Pine 12 S20°W 30 links

E-5 G.L.O. Addison P. Brewer D.S. August 1852.

Set post corner of section 8,9,16 and 17

Wit: Yellow Pine 12 N85.5°W 25 links

Yellow Pine 14 S46°E 14 links

Marvin E. Myers L.S. #31600 cert. of survey Oct. 1992 found plat mon. 18" West of center line of trail 8" R. Oak N70°W 34.38', 6" W. Pine S60°W 47.50', P. Pole N14°E 49.45', 1 1/4" pipe S45°E 3.10'

Consumer Power Company survey drawing H.A.Rhines June 1992. Found plat monument 18" West of centerline of trail Wit: 8" White Oak N70°W 34.38' S. Side nail 6" White Pine 60°W 47.50' N.W. side nail PK Telephone Riser S80°E 88.65' Top center P. Pole #181 N14°E 49.45' N.W. side nail&tag 1 1/4" pipe S45°E 3.10' center

Consumers Power Company survey map shows found 4" tile filled with concrete and a 1/2" rod in the center.

Wit: Triple black Oak N36°E 16.88'

16" White Oak N56°W 18.92'

12" Red Oak S23°W 26.35'

10" Oak S78°E 53.36'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

D-5 Found Concrete Monument

E-3 Found concrete filled clay tile with rerod.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-5 Found concrete monument

Wit: 6" Maple	N13°W	47.92'
*7" Oak	N65°W	34.15'
*Power Pole	N22°E	49.44'
*8" White Pine	S62°W	47.24'
Carsonite Post	North	1'±

* Old witnesses by others

E-5 Found concrete filled clay tile with rerod

Wit: Power Pole	North	23.83'
8" Oak	N81°W	33.29'
*10" Oak	S28°W	26.59'
3" Red Pine	S37°W	17.80'
Carsonite Post	North	1'±

* Old witnesses by others

Signed by:

Carl T. Kiiskila

Date:

11-27-01

Surveyor's Michigan License No.:

33981

