

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey

T 26N R 1W C-5

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Section

S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October 31, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

C-5 G.L.O. 1852 D. A. Pettibone set post for quarter corner.

Wit: 13" Pine N67°E 29 links  
13" Pine S76°E 26 links

May 1967 Robert Griffin RLS #13584 found an old wood stake and 1/2" x 35" Iron Rod on a narrow split of land and replaced it with 6" concrete monument.

Wit: 1" Pipe North 57.57'  
15" R. Pine S78°E 235.83'  
13" Aspen S56°E 39.90'  
6" Twin Maple S64°W 49.09'  
10" B. Oak N63°W 103.28'  
14" Aspen N41°W 38.00'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:  
C-5 Found Concrete Monument

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-5 Found Concrete Monument

Wit: 7" Twin Maple S71°W 49.12'  
16" B. Oak N58°W 103.36'  
8" W. Pine S28°E 11.35'  
6" W. Pine S26°E 4.97'  
4" x 4" Wood Post N06°E 1.5'  
N. Edge River South 44'  
S. Edge River North 66'



Signed by: Carl T Kiiskila

Date: 2-5-07

Surveyor's Michigan License No.: 33981