

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

|                                      |   |     |   |    |     |
|--------------------------------------|---|-----|---|----|-----|
| 1. Public Land Survey                | T | 26N | R | 1W | C-7 |
|                                      | T |     | R |    |     |
| 2. Property Controlling in Section   | S | T   | R |    |     |
|                                      | S | T   | R |    |     |
| 3. Miscellaneous Property in Section | S | T   | R |    |     |
|                                      | S | T   | R |    |     |

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on November 18, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

A. Description of original monument and accessories and/or subsequent restoration:

C-7 GLO 1852 D. A. Pettibone set post for corner.

Wit: 36" Pine N20°E 35 links  
12" Poplar S20°W 12 links

May 1967 Robert A. Griffin replaced found concrete monument with 6" diameter concrete monument.

Wit: 9" J. Pine N51°E 47.28'  
West End Culvert N12°E 169.08'  
4" Square Post East 33'  
33" W. Pine West 43.36'  
X Cut in Stone S29°W 61.61'

1909 Fargo Engineering found post at corner.  
No witnesses given.

1963 George Henning RLS #2240 found concrete monument for corner.

Wit: 12" J. Pine SE 44.0'  
10" J. Pine S36°W 95.0'  
8" J. Pine N51°E 47.0'  
36" W. Pine West 41.8'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

C-7 Found broken concrete monument

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-7 Set 1" X 32" pipe over found broken concrete monument

Wit: "X" in rock S29°W 61.53'  
30" W. Pine West 42.32'  
Sign Post S84°E 33.22'  
8" J. Pine N62°E 19.84'  
8" W. Pine N26°W 56.08'  
½" Iron bar East 32.90'



Signed by:

Carl T. Kiiskila

Date:

2-5-07

Surveyor's Michigan License No.:

33981