

SURVEY &
REMONUMENTATION

MAY 05 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
CRAWFORD COUNTY
RECORDED

For corners in
Crawford
(County)

Located In:

Corner Code #

7 JUN 96 9:48 A.M.

SANDRA MOORE
REGISTER OF DEEDS

1. Public Land Survey

T 26N R 3W

I - 4

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

LIBER

3 PAGE 234

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Marvin E. Myers, in a field survey on December, 19 95,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO-James Mullett 1839

Mon.-Set Post

WIT: 10" Tamarack S59°W 7 lks.

7" Cedar S30°E 14 lks.

N. Parker June 1971 L.1, pg.122

Mon.-Fd. 3/4" pipe on river bank

WIT: NBT 5" Poplar S21°W 61.40'

NBT 8" Tamarack S14°E 83.40'

G. Henning Nov. 1956

Mon.-None given

At mid-point on line:

on S. bank river

N. Parker Oct. 1979

Mon.-Fd. 1/2" Bar

WIT: 10" Poplar S35°W 56.25'

12" Tamarack S24°E 76.80'

River Bank North 2'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" X 3/4" Bar & DNR Cap #10068 under split rail fence

WIT: Fd. 14" Poplar S39°W 56.60'

River is 22' North

CRAWFORD COUNTY
PEER GROUP APPROVAL
DATE Dec 19, 1995

Marvin E. Myers
Marvin E. Myers, P.S.
County Surveyor

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon.- Fd. 5/8" x 3/4" Bar & Cap DNR Cap 10068 under split rail fence Set Standard Crawford County Mon.
stamped "I - 4 T26N, R3W #31600" in exact location of fd. 5/8" x 3/4" Bar

WIT: Set carsonite post N08°E 1.21'

Fd. nail E. side Poplar S39°W 56.03'

Nail & Tag SE side Poplar S39°W 56.38'

Nail & Tag N. side 4" Tamarack S80°W 49.12'

Nail & Tag NE side 8" Spruce S36½°E 39.60'

Water edge N08°E 20.00'



Signed by

Marvin E. Myers

Date

June 6, 1996

Surveyor's Michigan License No.

31600

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983