

# SURVEY & REMONUMENTATION

APR 07 1998

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Crawford Located In: Corner Code #  
(County)

1. Public Land Survey T 26NR 2W C-2  
T R  
T R  
T R

2. Property Controlling S T R  
In Section S T R

3. Miscellaneous S T R  
Property in Sec. S T R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
CRAWFORD COUNTY  
RECORDED  
19 DEC 97 2:37 P.M.  
SANDRA MOORE  
Register of Deeds & File  
Number

3 PAGE 285

I, Marvin E. Myers, in a field survey on 27 MAY, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.15 June 1852  
Darwin A. Pettibone D.S.  
Mon: Post  
Wit: 7" Pine N19°W 5 links  
12" Pine N65°E 31 links

George D. Henning R.L.S.  
Unrecorded Survey Sec.5 T26N R2W Oct 1955  
Mon - Found USBT & 1/2" iron, set monument  
Wit: 14" Norway Pine N50°W 82.8"  
10" Norway Pine S52 1/2°W 52.5'  
Fences West & North

George D. Henning R.L.S.  
Unrecorded Survey Sec.6 T26N R2W Oct 1955  
Mon - Found USBT & 1/2" iron, set monument  
Wit: 14" Norway Pine N50°W 82.8"  
10" Norway Pine S52 1/2°W 52.5'  
Fences West & North

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2													
3													
4													
5													
6													
7													
8													
9													
10													
11													
12													
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found concrete monument; found 28" Norway Pine with blaze N50°W 82.8'; found 22" Norway Pine S52 1/2°W 52.5'  
Accepted as a perpetuation of the Original Government Corner. Replaced with Standard Crawford County Monument.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Mon - Standard Crawford County Monument.

Wit: Set spike in South side 4" Jack Pine S59°E 39.83'  
Set spike in West side 14" Red Pine N32°E 45.33'  
Set spike in North side 6" Jack Pine N72°W 8.30'  
Set spike in Southeast side 18" Red Pine S44°W 34.90'  
Found 28" Norway Pine with blaze N50°W 82.8'  
Found 22" Norway Pine S52 1/2°W 52.5'

CRAWFORD COUNTY  
PEER GROUP APPROVAL  
DATE OCT 16, 1997

Marvin E. Myers  
Marvin E. Myers, P.S.  
County Surveyor



Signed by Marvin E. Myers  
Surveyor's Michigan License No. 31600

Date Dec 15, 1997