

CRAWFORD COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

| Crawford (County) | Located In: | Corner Code # |
|---------------------------------------|-------------|---------------|
| 1. Public Land Survey | T 26N R 2W | C - 8 |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S T R | |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

LIBER 3 PAGE 126

I, Marvin E. Myers, in a field survey on December, 19 93,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

| | |
|---|---------------------------|
| GLO - June 1852 D.A. Pettibone | 1985 USFS Haase |
| Mon. - Post | Mon. - Iron |
| WIT: 10" Pine S16°W 3.44 chs. | WIT: P. Pole S69°E 60.16' |
| No other timber | 7" J. Pine S28°W 57.39' |
| | Post East 79.72' |
| L.182, pg.360 Sept. 14, 1979 G. Henning | |
| Mon. - 3/4" Bar | |
| WIT: 5" J. Pine N26°W 50.95' | |
| 6" J. Pine S28°W 57.20' | |
| Power Pole S69°E 59.85' | |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" x 30" Bar of record 25'± West of centerline of North - South road. Verified location by measurement
to accessories of record and accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Mon. - Set Std. Crawford County Monument
WIT: Fd. Nail SE side 18" J. Pine S15°W 43.52'
Fd. 1/2" Bar in centerline N-S road S81°E 25.90'
Fd. Nail in National Forest Sign S87°E 79.75'
Fd. Nail N. side utility pole S63°E 60.22'
Set Std. Nail & Tag N. side 6" J. Pine N62°W 8.67'

Signed by Marvin E. MyersDate December 27, 1993Surveyor's Michigan License No. 31600DATE December 20, 1993

PEER GROUP APPROVAL