

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Crawford
County

Located In:

Corner Code //

Public Land Survey

T27N R1W

I-9

Property Controlling
in Section

S T R

Miscellaneous
Property in Sec.

S T R

Lot No. Recorded Plat
Private Claims

STATE OF MICHIGAN

COUNTY OF CRAWFORD

FILED FOR RECORD THIS
6th DAY OF June 1990
9:30 AM, IN LIBER 2
PAGE 359J. J. Williams
Register of Deeds

Register of Deeds Stamp & File Number

Norman C. Caldwell field survey on March 19 90
I hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

(I-9) Post set by Pettibone, July 21, 1852.
Thorn 10" S22°W .33 (21.78')
Thorn 9" N56°W .15 (9.90')

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I-9) LaGuire, 1934, placed a pipe & conc. block mon. from orig. BT NW
N11°E 11.9' 13" Elm
S01°W 26.1' 15" Popple
C.E. Ostling, LS 12026, fnd. pipe May 9, 1972.
N15°E 11.6' Elm
N89°E 25.1' Elm
rec. in L 1, pg 12
C.E. Ostling, LS 12026, fnd. 1 1/2" pipe Aug. 20, 1974
N76°W 61.8' P. Pole
S34°E 21.1' 6" Elm
N40°W 53.5' 9" Elm
rec. in L 1, pg 17

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-9) Sec. cor. 22,23,26&27, T27N-R1W

Fnd. 1 1/2" pipe per C.E. Ostling, rec. L 1, pg 17, (L 1, pg 12 trees gone) And is accepted as a careful and faithful perpetuation of the position of the original corner.
East 1' Carsonite Witness Post S88°E 47.7' old BT stump
N76°W 63.6' P. Pole (R)
S34°E 21.7' 7" Ash (R)
N50°E 67.5' 14" Ash
West 0.5' 4x4 conc. mon. 2' high

Signed by

Surveyor's Michigan License No.

12018

Date

April 26, 1990

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

