

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T..28. NR..2..W..  
T 28 N R 3 W  
T 29 N R 2 W  
T 29 N R 3 W

----- Crawford - Otsego - - COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 6, 1, 31, 36 - - - -

DESCRIPTION OF CORNER MONUMENT 1/2" Bar encased in 4" Concrete monument

WITNESSES TO CORNER 12" Red Pine Stump - N 90° E - 14 Links - - - - -

14" Red Pine Stump - S 40° E - 35 Links - - - - -

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this area. Corner had been previously located and perpetuated by G. F. DeLaMater, Registered Land Surveyor, of Gaylord.

Corner was rewitnessed November 22, 1952.

SURVEYORS SEAL

SIGNED

REGISTERED LAND SURVEYOR

DATE 2/20/53