

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey T 28N R 3W K-13
T R
2. Property Controlling in Section S 35 T 28N R 3W 7
S T R
3. Miscellaneous Property in Section S T R
S T R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 29, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2				5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-13 1839 - GLO - John H. Mullett - Set post cor sections 35 & 36. 7 - N 1/16 Cor., common to secs. 35 & 36, T28N, R3W

Birch 14 N84°W 14 links

Cedar 10 N57°E 08 links

1979 - MDNR - Kenneth J. Ostling P.S.#10068 - MDNR Survey map showing found brass cap mon from previous survey.

1986 - Certificate of Survey - L.255, pg.189 - Norman F. Parker P.S.#16939 - Shows MDNR standard monument

1999 - Certificate of Survey - Ronald C. Brand P.S.#43046 - Set 3/4"x10' iron pipe at corner location on 2/21/2000. Corner falls in beaver pond.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

K-13 Standard corner common to secs. 35 & 36, T28N,R3W 7 - N 1/16 Cor., common to secs. 35 & 36, T28N, R3W and secs. 1 & 2, T27N,RW

Found stamped 4" Brass "State of Michigan" cap on 4" diameter concrete cylinder. Found leaning cedar guard post +/-2' North. Accepted found State of Michigan monument as the best available evidence of the position of the original corner.

Found 3/4" iron pipe up 1' above ice in beaver pond per Brand Survey. Accepted found iron as best available evidence of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13 State of Michigan stamped 4"brass cap on 4" concrete cylinder. 7 - N 1/16 Cor., common to secs. 35 & 36, T28N, R3W

Wit:N10°E 32.00' to set N&T on W side 6" Cedar
S15°E 16.44' to fd. N&T on SW side 8" Cedar
N43°W 8.90' to set N&T on NE side 7" Cedar
N59°E 15.65' to set N&T on SE side 9" Cedar
N48°E 4.37' to fd. N&T on NW side 8" Cedar stump
Set Blue Carsonite Post 1' North

3/4"x10' Iron Pipe (placed 5/8" plastic cap#33981 inside pipe) No live trees within 300' of corner.
Wit:S55°E 41.32' to set N&T on S side 18" dead Cedar
S20°E 79.91' to set N&T on SW side 8" dead Cedar
S03°E 75.15' to set N&T on W side 7" dead Cedar
S64°W 63.15' to set N&T on SE side 10" dead Birch
Set Blue Carsonite Post w/loc. tag 1' North
Set 3" dia.x10' long Cedar post on N side of pipe.

Signed by:

Carl T. Kiiskila

Date:

1-6-10

Surveyor's Michigan License No.:

33981

