

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey

T \_\_\_\_\_ R \_\_\_\_\_  
T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling  
in Section

S 35 T 28N R 3W 5  
S 35 T 28N R 3W 12

3. Miscellaneous  
Property in Section

S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

4. Lot No: \_\_\_\_\_

Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on February 9, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

5 - CN 1/16 Cor., Section 35, T28N, R3W

None

12 - CS 1/16 Cor. Section 35, T28N, R3W

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

5 - CN 1/16 Cor., Section 35, T28N, R3W

Set 5/8"x34" CIR#33981 per standard BLM procedure.  
Found no other evidence to dispute the location for the corner.

12 - CS 1/16 Cor. Section 35, T28N, R3W

Set stamped 2" Aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found 1/2" rebar per Cert. of Survey - B.139, p.120 - Norman F. Parker, P.S.#16939 - did not accept Parker's position due to being four feet too far north for a single proportion position on the South half of the N-S quarter line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5 - CN 1/16 Cor., Section 35, T28N, R3W

5/8"x34" CIR#33981

Wit: N18°E 9.46' to set N&T on W side 8" S. Maple  
S84°E 22.31' to set N&T on S side 6" S. Maple  
S14°E 32.92' to set N&T on SW side 9" S. Maple  
S87°W 20.55' to set N&T on S side 12" S. Maple  
Set Blue Carsonite Post w/loc. tag 1' North

12 - CS 1/16 Cor. Section 35, T28N, R3W

5/8"x34" CIR#33981

Wit: N03°E 48.53' to set N&T on E side 13" S. Maple  
S70°E 12.35' to set N&T on S side 11" S. Maple  
S24°W 15.73' to set N&T on W side 9" Twin S. Maple  
N87°W 44.32' to set N&T on S side 11" S. Maple  
N06°E 4.17' to fd. 1/2" rebar  
Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

1-6-10

Surveyor's Michigan License No.:

33981

