## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

For Corners In:				
Crawford (County)	Located in	Corner Code		
(County)				
Public Land Survey	T 28N R 3W			
Property Controlling     in Section     S	T R			
S	— т —— п			
3. Miscellaneous	- · ·	= 112		
Property in Section S	_ T R	±= ,:1	Pariston of Pariston of Pariston	
4 Lot No.	ded Dies.	agyer N	Register of Deeds Stamp & File Number	
<del></del>	ded Plat:		ABCDEFGHIJKLN	A
5. Private Claims:		<del>-</del>	2 6 5 4 3 2	
I, Carl T. Kiiskila, in a field survey on June 09, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				
NOTE: Not more than 2 corner be recorded on this certificate.	s, all in the same towr	and range, may	25 26 25	
23 root dod on this certificate.			11	-
			12 31 32 33 34 35 36 -	1
			13	1
A. Description of original monument and accessories and/or subsequent restoration:				
J-7 <b>1857 –</b> GLO – Walter Wa	rner – Set quarter sed	ction K-	7 1857 – GLO – Walter Warner – Reestablished	l old
post. Wits: Hemlock 18 S2	E920' 14/ 40 limbs		corner of sections 13,14,23 and 24	
Sugar 14 N1°30			Wits: Beech 12 N55°W 11 links Beech 14 S65°E 27 links	
3		€¥	Deedi 14 303 E 27 IIIKS	
		-	The second secon	
	9			
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:				
	int fitting GLO record ly well. Found no othe	distances K-7	Found a 3/4" x 28" Pipe fitting occupation North West and GLO record distances South and We reasonably well. Found no other evidence to d the position of this corner.	est
			8	
C. Description of monument for c	orner and accessories e	stablished to per	petuate locating the position of the corner:	
J-7 Set a 4" aluminum DNR ( Wit: N13°E 13.08' to set	cap on 1"x36" galvani N&T on E side 4" Be N&T on N side 7"-12" I&T on W side 6" S.M N&T on S side 6" Iron blaze of all witnesses	zed pipe K-7 ech Wit Maple flaple wood	Set a 4" aluminum DNR cap on 1"x36" galvaniz N45°E 39.18' to set N&T on SE side 4"&11" CMaple N46°E 32.46' to set N&T on SW side 16" Bee S59°W 37.51' to set N&T on SE side 14" Qua Maple N55°W 52.38' to set N&T on NE side 5" Maple Set Blue Carsonite Post 15' West	luad ech d
	= 11 = 1	· 0	CA	ST AND
Signed by:	T /Kush	le	Date: / - 6 - 10 14 LAN	1D
Surveyor's Michigan License N	No.: 33981	18 100 18 100	No	4 <i>0</i>
		Fayle 1	339	21 WIFE
	7 8	FORM APPROVED E	Y MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS	D SUN

Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995