

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey

T

R

2. Property Controlling  
in Section

S 23

T

28N

R 3W

8

S 23

T

28N

R 3W

11

3. Miscellaneous  
Property in Section

S

T

R

S

T

R

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kliskila, in a field survey on February 10, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

8 - CW 1/16 Cor., Section 23, T28N, R3W

None

11 - SW 1/16 Cor. Section 23, T28N, R3W

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

8 - CW 1/16 Cor., Section 23, T28N, R3W

Set 5/8"x34" CIR#33981 per standard BLM procedure.  
Found no other evidence to dispute the location for the corner.

11 - SW 1/16 Cor. Section 23, T28N, R3W

Set 5/8"x34" CIR#33981 per standard BLM procedure.  
Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8 - CW 1/16 Cor., Section 23, T28N, R3W

5/8"x34" CIR#33981

Wit: N42°W 28.20' to set N&T on W side 9"&10" Twin  
S. Maple  
N05°E 5.59' to set N&T on E side 4"&7" Twin  
S. Maple  
S58°E 29.39' to set N&T on NE side 9" Quad  
S. Maple  
S24°W 20.00' to set N&T on NW side 5" Ironwood  
There is barb wire fence running South and West.  
Fence corner is 29' South of corner & 12' East.  
Set Blue Carsonite Post w/loc. tag 1' North

11 - SW 1/16 Cor. Section 23, T28N, R3W

5/8"x34" CIR#33981

Wit: N87°E 51.28' to set N&T on N side 10" S. Maple  
N25°E 39.72' to set N&T on E side 6"&10" Twin  
S. Maple  
N25°W 10.81' to set N&T on SW side 20" S. Maple  
S36°E 6.09' to set N&T on W side 16" S. Maple  
There is barb wire fence running North and West.  
Fence corner is 20' North of corner & 6.5' East  
Set Blue Carsonite Post w/loc. tag 1' North

Carl T. Kliskila

Surveyor's Michigan License No.: 33981

1-6-10

