

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Crawford

(County)

Located In

Corner Code #

1. Public Land Survey	T	28N	R	3W	I-8,K-10
	T		R		
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: \_\_\_\_\_ Recorded Plat: \_\_\_\_\_

5. Private Claims: \_\_\_\_\_

I, Carl T. Kiiskila, in a field survey on September 27, 2008 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-8 1857 - GLO - Walter Warner - Reestablished old quarter section corner.  
 Sugar 12 S20° W 29 links  
 Sugar 10 N87°30' E 30 links  
 1969 - Unrecorded survey Norman Parker RLS #16939 placed a ¾" x 36" pipe for ¼ corner.  
 Wits: PK nail in W. Pine Stump N45°E 35.8'  
 PK nail in P. Pole S40°E 58.4'  
 1995 - Liber 3 p. 223 Robert F. Mitchell found 1 ¼" as a perpetuation of the original corner.  
 Set spike SW sd. P.P. S32°E 58.52'  
 Set spike SW sd 8" Poplar N17°W 20.3'  
 Set spike S. sd 8" Poplar N85°E 44.45'  
 Set spike S sd 6" Poplar S58°W 14.82'  
 2005 - Mitchell and Associates #43046 Certificate of Survey found 1 ½" pipe  
 Fd spk power pole S32°E 58.52'  
 Fd spk rotted stump N17°W 20.30'  
 Set N/T 4" R. Pine N19°W 26.90'  
 Set N/T 6" R. Pine S35°W 38.70'  
 Set N/T 12" W. Birch N65°E 64.35'

K-10 1857 - GLO - Walter Warner - Reestablished old quarter section corner.  
 Beech 14 S81° W 37 links  
 Beech 12 N20°E 46 links  
 Norman F. Parker R.L.S. #16939  
 L.C.R.C. Liber 2, page 124  
 Mon. Found angle iron set by Henning R.L.S. from old Witnesses  
 Wits: Aluminum tag in 16" Maple S39°E 5.0' (Henning)  
 Aluminum tag in 12" Cedar N64°E 47.8'  
 1999 Liber 4 Page 74 Crawford County Remonumentation Program Marvin Myers P.S. #31600  
 Mon: Standard Crawford County Monument  
 Wits: Set spike in W. face 6" Ash S32°W 31.20'  
 Set spike in SW face 18" Maple S39°E 5.65'  
 Set spike in E face 14" Cedar N39°E 58.54'  
 Set spike in S face 4" Yellow Birch N34°E 11.90'  
 Set Carsonite Post East 1" ±

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

I-8 Found a ½" bar with P.S. cap #28417 and #30079 along side a bent 1" pipe. Replaced ½" bar with standard DNR Monument.

K-10 Found all of the witnesses recorded in 1999 Crawford County Remonumentation Program, Monument was removed. Re-established the East ¼ corner of section 26 from M. Myers Remonumentation Program Witnesses.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-8 Set a standard DNR Monument  
 Wits: S34°E 58.68' to set PK nail & Tag SW side P. Pole  
 N81°W 4.45' to Found 1" Pipe  
 S24°W 38.57' to Fd Nail & Tag #43046 NW side  
 10" R. Pine  
 N17°W 26.90' to fd Nail & Tag W side 7" Scotch Pine  
 N57°E 64.58' to fd Nail & Tag S side 12" Poplar  
 Center N-S Drive East 7'

K-10 Set a 1" x 48" pipe with standard DNR Cap  
 Wits: N34°E 11.90' to fd spike in 7" Y. Birch  
 S29°E 5.65' to fd spike in 21" Maple  
 N39°E 58.52' to fd spike in 17" Cedar  
 S33°W 31.28' to fd spike in 7" Ash

Signed by:

Carl T. Kiiskila

Date:

1-6-10

Surveyor's Michigan License No.:

33981

