

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Charlevoix

(County)

Located In

Corner Code #

1. Public Land Survey

T

R

T

R

2. Property Controlling  
in Section

S

14

T

32N

R

4W

3

S

14

T

32N

R

4W

4

3. Miscellaneous

Property in Section

S

T

R

S

T

R

Register of Deeds Stamp & File Number

4. Lot No:

Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on May 19, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.**

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

3 - N 1/16 Cor., common to Sec.'s 14 & 15, T32N, R4W

4 - NW 1/16 Cor., Section 14, T32N, R4W

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

3 - N 1/16 Cor., common to Sec.'s 14 & 15, T32N, R4W

4 - NW 1/16 Cor., Section 14, T32N, R4W

Fd. 4" dia. conc. mon. with 1/2" rebar. Top was broken and bent a little. Straightened rebar and placed plastic cap #33981 on it. Mon. is less than 0.3' from calculated position. Accepted fd. mon. as the best available evidence for the position of the corner.

Set stamped 2" alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3 - N 1/16 Cor., common to Sec.'s 14 & 15, T32N, R4W

4 - NW 1/16 Cor., Section 14, T32N, R4W

Fd. 4" dia. conc. mon. with 1/2" rebar, added plastic cap #33981.

Witnesses:

N37°E 17.04' to set N&T on E side 11" S.Maple  
S59°E 23.24' to set N&T on SW side 9"&12" Twin S.Maple  
S06°E 31.14' to set N&T on W side 13" S.Maple  
S89°W 8.17' to set N&T on S side 17" S.Maple  
Set Blue Carsonite Post w/loc. tag 1' North

Stamped 2" Aluminum cap on 5/8"x34" rebar

Witnesses:

N24°E 32.98' to set N&T on NW side 7"&12" Twin S.Maple  
S46°E 11.41' to set N&T on W side 4" S.Maple  
S34°W 25.50' to set N&T on SE side 12" S.Maple  
N50°W 25.10' to set N&T on NE side 7" S.Maple  
Set Blue Carsonite Post w/loc. tag 1' North

Signed by:

Carl T. Kiiskila

Date:

1-19-10

Surveyor's Michigan License No.:

33981

