

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Charlevoix

(County)

Located In

Corner Code #

1. Public Land Survey	T	32N	R	4W	I-6		
	T		R				
2. Property Controlling in Section	S	T	R				
	S	T	R				
3. Miscellaneous Property in Section	S	14	T	32N	R	4W	9
	S		T		R		

Register of Deeds Stamp & File Number

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on November 18, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-6 - 1/4 Corner comm. to sec.'s 14&15, T32N, R4W

9 - CE 1/16 corner, section 14, T32N, R4W

1850 - GLO - William Burt - Set Hemlock 1/4 section post.

Sugar 9 N32°W 18

Sugar 18 S20°E 9

2007 - Cert. of Survey, L. 826 p.384 - Jason Caverson, P.S.#46658 - Fd. Charlevoix Co. mon. N65°E 17.76' fd. spk. 15" Maple; S45°W 11.90' fd. spk. 10" Ironwood; N20°W 35.45' fd. spk. 15" Maple; S40°E 62.91' fd. spk. 18" Maple.

1981 - Cert. of Survey - Sherman A. Chamberlain, P.S.#25834 - Shows setting "T" iron midway and online between J6 and K6.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

I-6 - 1/4 Corner comm. to sec.'s 14&15, T32N, R4W

9 - CE 1/16 corner, section 14, T32N, R4W

Found a 3" dia. brass. cap on 4" dia. conc. cylinder. Accepted found mon. as the best available evidence of the position of the original corner. Found no other evidence to dispute the location for the corner.

Found "T" iron w/washer#25834 per Chamberlain survey in 1981. Corner is 70' South of a gate on a 2-track trail road. Accepted found "T" iron as the best available evidence for the position of the corner. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-6 - 1/4 Corner comm. to sec.'s 14&15, T32N, R4W

9 - CE 1/16 corner, section 14, T32N, R4W

Stamped 3" dia. brass. cap on 4" dia. conc. cylinder.

Witnesses:

*N59°E 17.70' to set N&T on SE side 8" S.Maple

S25°E 27.54' to set N&T on SW side 4" Ash

S82°W 23.33' to set N&T on N side 4" Beech

*N27°W 35.34' to set N&T on SW side 13" S.Maple

Set Blue Carsonite Post 1' North

"T" Iron with washer#25834 (Placed 4 cobble stones around iron)

Witnesses:

N03°E 26.29' to set N&T on W side 16" S.Maple

S61°E 25.52' to set N&T on SW side 6" S.Maple

S01°W 15.77' to set N&T on E side 12" Twin S.Maple

N77°W 6.57' to set N&T on S side 13" Basswood

Cemented in metal fence post to SE 0.3'

Set Blue Carsonite Post w/location tag 1' North

* Previous recorded witness.

Carl T. Kiiskila

Surveyor's Michigan License No.:

33981

1-19-10

