

SURVEY & REMONUMENTATION

OCT 19 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Charlevoix</u> (County)	Located In:	Corner Code #
1. Public Land Survey	32N R 7W	L-13
	T R	
	31N R 7W	L-1 ANTRIM
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property In Sec.	S T R	
	S T R	

STATE OF MICHIGAN
COUNTY OF CHARLEVOIX
RECEIVED RECORD

98 SEP -8 PM 2:13

Charles E. Boss
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Wayne E. Boss JULY 98
I, _____, in a field survey on _____, 19____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

L-13	OCTOBER 1856	DECEMBER 1966, MARY C. FEINDT, P.S.
	EDWARD D. ATWATER, DEPUTY SURVEYOR	IRON FOUND, NO WITNESSES NOTED
	SET QUARTER CORNER	IRON DEPICTED IN ROAD RIGHT OF WAY
	CEDAR 15 INCH N23°E 30 LINKS	ON SKETCH FOR GERALD WATT
	CEDAR 17 INCH S45°W 18 LINKS	
	NO OLD 1/4 CORNER FOUND	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

L-13 APRIL 1998 FOUND 1/2" IRON AT WEST EDGE OF ASPHALT OVER METAL CULVERT
12" CEDAR S22°W 29.90' FOUND NAIL & BLAZE
ELECTRIC POLE N 71°W 78.50' WITH RIBBON
1" STEEL SHAFT N85°W 49.87' TO CORNER USED BY ARTHUR LENOX
1 M-13 TO L-13 GLO 40 CHAINS (2640.0') MEASURES N89°06'33"W 2623.25'
L-13 TO K-13 GLO 40 CHAINS (2640.0') MEASURES N89°20'08"W 2615.89'

Charlevoix Co. Surveyor
APPROVED
Signature *Mary C. Feindt*
Date: *Aug. 13, 1998*

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13 PLACED STEEL CHARLEVOIX COUNTY MARKER
AT WEST EDGE OF ASPHALT
12" CEDAR S22°W 29.90' SET NAIL & TAG
1" STEEL SHAFT N85°W 49.87'
ELECTRIC POLE N71°W 78.50' SET NAIL & TAG
12" CEDAR N38°E 49.01' SET NAIL & TAG



AND IS ACCEPTED AS A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER

Signed by *Wayne E. Boss*
Surveyor's Michigan License No. 20703

Date Aug. 24, 1998