

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 33 N. 8. R. 4 W.	C-13; E-11
2. PROPERTY CONTROLLING IN SECTION	T. S. R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. S. R. E. W.	
4. LOT NO.	RECORDED PLAT	
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on December 19, 1985, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

B. (Continued):

~~Accreditation of the Michigan State Board of Registration for Land Surveyors~~  
E-11 - Fd. Schaaf pipe monument (2" x 36" pipe w/conc. base), S55°36"E, 175.4'.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
C-13 - Fd. Marcus Schaaf 2" pipe mon. for Sec. cor. comm. to Sec's 31&32 (T33N-R4W) & Sec's 5&6 (T32N-R4W). Fits U.S. stream tie 1198'± N., 279'S. & E.A. Robinson tie's west 1-mile (to very definite spring that soaks into ground & twp. cor.) along N. line of Sec. 6 (T32N-R4W); see Hudson (32-4), Bk. C-296, pg. 10, dated May 14, 1906; notes in jury room in ct. hse.  
E-11 - Re-estb. SE cor. of Sec. 29 at dbl. distance & on line across fd. ¼ cor. & Sec. Cor. to W. E.A. Robinson in 1902 estab. the S¼ cor. & W 1/8 on S. line of Sec. 29 by single proportion bet. SE & SW cor's of Sec. 29; see Chandler Bk., pgs. 4-9 on file at Jury Rm. in ct. hse. Ctr. of E-W gravel road is 10'± south (road in slight curve here).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-13			E-11		
Fd. 2" pipe w/conc base & replaced w/DNR mon. & set cedar post			Drove 5/8" x 34" rerod w/RLS cap in gravel road		
6" Maple	N26°W	8.6'	5" Maple	N30°E	37.5'
3" Maple	N68°E	13.5'	6" Cedar	N32°W	44.7'
7" Maple	S62°E	22.0'	8" Cedar	S20°E	78.4'
9" Maple	S45°W	26.9'	8" Cedar	S04°W	77.9'
E-W trail (drivable)	North	107'	Set cedar post w/loc tag	South	50'

SIGNED BY Carl F. Roser 02-07-86 DATE

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE

MICHIGAN REGISTERED LAND SURVEYOR



(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

CHARLEVOIX COUNTY