

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:

Charlevoix  
(County)

Located In

Corner Code #

|                                      |   |     |   |     |     |    |   |
|--------------------------------------|---|-----|---|-----|-----|----|---|
| 1. Public Land Survey                | T | 33N | R | 4W  | J-7 |    |   |
|                                      | T |     | R |     |     |    |   |
| 2. Property Controlling in Section   | S | 23  | T | 33N | R   | 4W | 2 |
|                                      | S |     | T |     | R   |    |   |
| 3. Miscellaneous Property in Section | S |     | T |     | R   |    |   |
|                                      | S |     | T |     | R   |    |   |

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on October, 1999 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

|    |    |   |    |   |    |   |    |   |    |   |    |   |
|----|----|---|----|---|----|---|----|---|----|---|----|---|
| A  | B  | C | D  | E | F  | G | H  | I | J  | K | L  | M |
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |
| 4  | 7  |   | 8  |   | 9  |   | 10 |   | 11 |   | 12 |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |

A. Description of original monument and accessories and/or subsequent restoration:

J-7 G.L.O.-Charles W. Cathcart D.S.-1841  
A Hemlock 24 inches the quarter section post.  
No witnesses given.

2- This corner position was not established during the original government survey.

Page 225 county surveyors recorded September 1882 E.K.  
Robinson county surveyor found old Hemlock tree no new witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

J-7 Re-established the south quarter corner of section 14 by single proportionate measurement between corners I-7 and K-7.

2 Established the northeast corner of the northwest quarter of the northeast quarter of section 23 per standard BLM instructions for the subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7 Set 1"X32" Iron pipe with aluminum DNR cap  
Wit: 5"X8" Twin Maple S70°E 14.66'  
4" Maple S85°W 5.95'  
4" Maple N25°W 16.04'  
6" Maple N21°E 16.98'  
Carsonite post North 1'

2- Set 5/8"X32" rerod with cap  
Wit: 10" Maple N81°W 11.86'  
4" Maple N25°W 11.32'  
4" Maple N58°E 6.16'  
10" Maple S01°W 8.16'  
Carsonite post North 1'

Signed by:

Carl T Kiiskila

Date:

1-26-00

Surveyor's Michigan License No.:

33981

