

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>33</u> N. <u>5</u> W.		<u>H-7, G-7, G-6, H-6</u>
2. PROPERTY CONTROLL- ING IN SECTION_____ T. _____ N. _____ E.		
3. MISCELLANEOUS PROPERTY IN SECTION_____ T. _____ N. _____ E.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on November 18, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

XX  
C. Continued:

G-6			H-6		
Fd. T. Ir.; Drove 1" x 3' pipe over			Set 5/8" x 3' re-rod w/cap & cedar post		
T. Ir. & Ced. Post			20" Maple	S30°E	7.3
5" Cedar	N30°W	15.2	4" Maple	N70°E	25.2
8" Cedar	S10°E	28.3	11" Maple	N10°W	27.0
7" Ash	N80°W	17.2	Fd. "T" Ir.	S15°58'W	9.75
20' wide creek	West	60'±			

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:  
H-7 Fd. 3/4" pipe that fits survey of Sec. 15 by RLS Larry Feindt.  
G-7 Fd. 1" Ir. rod that fits M.S.H.D. Wits and survey of Sec. 15 by RLS Larry Feindt  
G-6 Fd. "T" iron by RLS Larry Feindt for W1/4 corner of Sec. 15.  
H-6 Established center of Sec. 15 at intersection of one-quarter lines

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-7			G-7		
Fd 3/4" Pipe w/RLS cap #3920 & added Ced.			Fd. 1" Ir. Rod & set Ced. Post w/loc tag		
Post w/loc tag.			*18" W. Pine	N70°E	71.10
7" Maple	S70°W	6.8	*9" Cedar	N55°E	60.40
*8" Maple	S45°E	22.8	*P. Pole	S65°W	66.35
6" Maple	N50°W	65.8	Ctr. line E-W Gravel Rd. N		15'±
*=Old Wits			*=Old Wits.		

SIGNED BY Carl F. Roser 01-12-82 DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

MELROSE TOWNSHIP  
CHARLEVOIX COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971  
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET