

FEB 22 2001

STATE OF MICHIGAN  
COUNTY OF CHARLEVOIX  
REGISTER OF DEEDS

SECTION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

00 DEC 21 AM 9:01

For corners in

*Charlene B. Justice*  
REGISTER OF DEEDS

Charlevoix \_\_\_\_\_ Located In: \_\_\_\_\_ Corner Code # \_\_\_\_\_  
 (County)

1. Public Land Survey T 33N R 8W E-3 \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_  
 T \_\_\_\_\_ R \_\_\_\_\_

2. Property Controlling S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 in Section S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

3. Miscellaneous S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_  
 Property in Sec. S \_\_\_\_\_ T \_\_\_\_\_ R \_\_\_\_\_

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
 5. Private Claims \_\_\_\_\_

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3					●								
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Wayne E. Boss, in a field survey on November, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-3 October 22, 1841 Charles W. Cathcart, D.S. About 1970 M.C. Feindt, P.S.  
 Set section corner post Placed T-iron  
 1) Beech 18" S45°W 2 links (1.32')  
 2) Beech 4 S30°E 6 links (3.96')

June 14, 1994 Arthur R. Ranger, P.S.  
 Found T-iron  
 no witnesses noted

Charlevoix Co. Surveyor  
 APPROVED  
 Signature *Mary C. Feindt*  
 Date: *12-7-00*

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-3 November 7, 2000  
 Found T iron in fence link to West and East with evidence of old fence to North  
 3) 32" Maple N10°E 35.45 found nail

E-4 to E-3 GLO 40 chains (2640') measures 2653.43' ARR. 2654.18  
 E-3 to E-2 GLO 40 chains (2640') measures 2642.20'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-3 Placed Charlevoix County steel marker  
 3) 32" Maple N 10°E 35.45' Used nail as found  
 1) 2x3x3" Rock West 7.86' Made small hole in top  
 2) 1 1/2" Cherry East 40.75' No nail placed  
 3) Fence post West 25.68 placed nail

And is accepted as a careful and faithful reestablishment of the position of the original corner.

Signed by \_\_\_\_\_  
 Surveyor's Michigan License No. \_\_\_\_\_

Date *12/15/2000*

