

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Cheboygan
(County)

Located In:

Corner Code ~~77~~

1. Public Land Survey	T <u>33N</u> R <u>1E</u>	<u>M-1,2</u>
	T <u>33N</u> R <u>1E</u>	<u>M-1,7</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u>1</u> T <u>33N</u> R <u>1E</u>	<u>7</u>
	S <u>1</u> T <u>33N</u> R <u>1E</u>	<u>9</u>
3. Miscellaneous	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
 5. Private Claims

I, Carl R. Johnson, in a field survey on August 26, 19 87, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-1,2 - Set on township line S89°51'52"E, 28.0ft from NE corner of Section 1, which falls in river.

M-1,7 - Set on E. line of Section 1, S01°13'53"W, 83.23 ft. from NE corner of section 1, which falls in river.

7 - Set by single proportionate measurement between E $\frac{1}{4}$ corner and NE corner of Section 1.

9 - Set by standard survey procedure for subdivision of a section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-1,2 - Witness Corner

DNR Mon. & cedar post
 Maple 12" S14°W 24.4'
 Maple 10" N74°W 33.8'

M-1,7 - Witness Corner

DNR MON. & cedar post
 Maple 8" S66°W 26.3'
 Ash 8" N28°W 18.1'

7 - N 1/8 Cor. East Side Sec. 1

5/8" bar w/cap
 Maple 8" S76°W 70.1'
 Maple 16" N60°E 15.6'

9 - E 1/8 on E-W $\frac{1}{4}$ Line

5/8" bar w/cap
 Reference marker and nail on
 24" Spruce S4°W 36.59'
 Fence Post N32°E 38.06'
 Fence Post N30°W 43.64'
 Cedar Post N5°E 30.0'

Signed by Carl R. Johnson
 Surveyor's Michigan License No. 30083



Date 1/4/88