

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N. R. 1 E


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 19 and 30

CORNER MONUMENT Set 1" pipe with 1/4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED March 31, 1966

WITNESSES TO CORNER.....



7" Cedar S 24 W 2.4'

5" Cedar N 55 E 18.9'

AND NE USBT good

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was restored while making a resurvey in this township.
Set corner from NE USBT which has fallen over but still has evidence of
face and scribe marks. Could find no post in swamp.

SURVEYOR'S SEAL

SIGNED

Kenneth J. Ostling
REGISTERED LAND SURVEYOR #18060

DATE April 14, 1966