Louving

## MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

## LAND CORNER RECORD

T 34 NR 1 E

						Chebo	ygan		COUNT	Y
DESCRIPTION	0	F CORNER	1/4	gor <u>n</u>	šī Čomāo	n_to_	Section .	18 4_a	nd 9	
DESCRIPTION	OF	CORNER	MONU	MENT	Chisei	ed cr	oss in	pTēćķ	<u>top</u>	
WITNESSES	то	CORNER .					- <b></b>			
			MSHD	ROW	marker		N27E		72.7 feet	
			NSHD	ROW	marker		SIE	<u>-</u> 	53.6 feet	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was established at midpoint, on line between section corners by Forestry Division surveyor while making a survey in Section 9. No evidence of previous corner, nor could one be found by MSHD survey crews prior to road reconstruction. Checks good with fence line south through Section 9. Falls about 6.5 south of centerline of M-68.

Corner marked and witnessed November 11, 1959.

SIEVEYORS SEAL

SIGNED LEND SURVEYOR DATE 11/16/59