

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Cheboygan Located In _____ Corner Code # _____
(County)

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 12 T 34N R 1W 8
S 12 T 34N R 1W 12
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Carl T. Kiiskila, in a field survey on February 2, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|----|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | | 5 | | | 4 | | | 3 | | 2 | 1 |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | | 9 | | | 10 | | 11 | | 12 |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

A. Description of original monument and accessories and/or subsequent restoration:

8-CW 1/16 Corner, Section 12, T34N,R1W

12-CS 1/16 Corner, Section 12, T34N,R1W

None

None

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

8-CW 1/16 Corner, Section 12, T34N,R1W

12-CS 1/16 Corner, Section 12, T34N,R1W

Set stamped 2" dia. alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

Set stamped 2" dia. alum. cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

8-CW 1/16 Corner, Section 12, T34N,R1W

12-CS 1/16 Corner, Section 12, T34N,R1W

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Stamped 2" dia. aluminum cap on 5/8"x34" rebar

Witnesses:

N20°E 87.05' to set N&T on E side 9" W. Pine
N29°E 51.07' to set N&T on SE side 16" R. Maple Clump
S31°E 21.48' to set N&T on E side 11" Spruce
N86°W 76.08' to set N&T on S side 5" Cherry
Set Blue Carsonite Post w/location tag 1' North

Witnesses:

N38°E 95.75' to set N&T on S side 9" R. Maple Clump
S15°E 126.35' to set N&T on E side 30" R. Maple
S24°W 65.87' to set N&T on SE side 8" R. Maple Clump
N62°W 41.62' to set N&T on SW side 22" R. Maple (Quad)
Set Blue Carsonite Post w/location tag 1' North

Signed by:

Carl T. Kiiskila

Date:

6-15-10

Surveyor's Michigan License No.:

33981

