

SURVEY &  
REMONUMENTATION

Walker  
MAY 05 1997

COMMISSION

RE MONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECEIVED  
FDP RECORD

96 NOV 25 PM 1:06

*James Gray*  
CLERK/REGISTER  
CHEBOYGAN COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

For corners in

Cheboygan

(County)

Located in:

Corner Code #

1. Public Land Survey

T 34N R 1W

M-6

T      R     

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S     

T      R     

S     

T      R     

3. Miscellaneous  
Property in Sec.

S     

T      R     

S     

T      R     

4. Lot No.     , Recorded Plat     

5. Private Claims     

Brian K. Fullford

in a field survey on August, 19 96

do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O.

Set 1/4 Section Post

7" Beech S22°W 17 Links

8" Maple N41°E 19 Links

1966 D.O.C. Corner Record

Kenneth Ostling #10068

Set 1" Pipe w/4" Brass Cap

Set Proportionate Measurement

9" Red Oak N45°W 20.7'

8" Red Oak N56°E 13.6'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" Pipe with Department of Conservation 4" Brass Cap

12" Red Oak N49°W 20.51' (Ostling Witness)

12" Red Oak N56°E 13.98' (Ostling Witness)



LIBER 010 PAGE 208

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6 Found 1" Pipe with Department of Conservation 4" Brass Cap. Accepted as a careful & faithful re-establishment of the position of the original corner.

12" Red Oak N56°E 13.98' Set Tag

4" Maple S11°W 10.30' Set Tag

5" Red Oak S70°W 20.81' Set Tag

12" Red Oak N49°W 20.51' Set Tag

THIS CORNER IS ALSO DESIGNATED AS CORNER CODE #A-6, IN T34N-R1E.

Witnessed by B. K. Fullford  
Surveyor's Michigan License No. 41099

Brian K. Fullford, PS

Date 10/22/96

