

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 N.R. 1 W


Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 corner common to Sections 1 - 2

CORNER MONUMENT Set 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 9-19-66

WITNESSES TO CORNER.....



CIRCLE CORNER REGISTERED

9" Cedar S 26 W 3.5'

6" Cedar N 38 E 34.9'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set by proportionate measurement between section corners while making a survey in this township.

SURVEYOR'S SEAL

SIGNED Kenneth J. Ostling DATE Nov. 18, 1966
REGISTERED LAND SURVEYOR #10068