

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 34 NR. 1 W. 1

Cheboygan COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 10 & 11

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER 12" Cedar - S 52 W - 97 Links

8" Cedar - N 29 W - 81 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by the Forestry Division survey crew, while working
in this area. Two original B.T.'s in place, in fair condition.

Corner was placed and witnessed August 2, 1951.

SURVEYORS SEAL

SIGNED Dean C. L. L. L. DATE 8/2/51
REGISTERED LAND SURVEYOR